

A close-up, artistic photograph of a guitar's body, focusing on the pickup area. The guitar has a dark wood finish with a light-colored wood stripe. A black pickup is mounted on the body, and several strings are visible. The background is dark and out of focus.

Seybold

GITARRENSCHMIEDE

REPARATUREN 2018

STAND 27.11.2017

SETUP

E-GITARRE EINSTELLEN	30,00 €
E-GITARRE MIT TREMOLO	50,00 €
AKUSTIK GITARRE	45,00 €
SATTELKERBEN NACHARBEITEN	25,00 €

HALS UND BÜNDE

NEUBUNDIERUNG OHNE BINDING	220,00 €
NEUBUNDIERUNG GEBUNDENES GRIFFBRETT	250,00 €
BÜNDE ABRICHTEN	90,00 €
NEUER SATTEL (KNOCHEN ODER KUNSTSTOFF)	45,00 €
STEGEINLAGE ERSETZEN (KNOCHEN ODER KUNSTSTOFF)	45,00 €
HALS ABRICHTEN	520,00 €
AKUSTIKGITARREN NECK RESET	520,00 €

ELEKTRONIK

EINEN TONABNEHMER TAUSCHEN	40,00 €
JEDER WEITERE TONABNEHMER TAUSCHEN	20,00 €
SCHALTER / POTI / BUCHSE TAUSCHEN	20,00 €

FINISH UND CO

KORPUS E-GITARRE	AB 300,00 €
HALS	AB 150,00 €

VIELES WEITERE AUF ANFRAGE!